

Email: mailbox@sealxpert.com



## **SealXpert Products**

## **Leak Repair Application Note 33**

Pipe Material: Carbon Steel Pipe

Pipe Medium: Sea Water 60" (1500mm) Pipe Size:

150 psi Pipe Pressure: 30°C Temperature:

Leak Location: Weld joint Leak

A seawater cooling pipe in a power plant was facing a leak at weld joint near the pipe flange. The pipeline cannot be shutdown for repair or replacement and SealXpert™ products were applied and the repair was completed successfully while the system is in operation.

Firstly, the leak area was cleaned of any paint or loose debris from the pipe surface. Thereafter, Seal Stic™ Quick Cure Epoxy Stic was applied onto the leak area with the help of a sheet metal and SealXpert™ Stainless Steel Pipe Clip.

Once the Seal Stic™ Quick Cure Epoxy Stic was cured. SealXpert™ Repair Putty was applied onto the entire pipe circumference and flange area. Finally, the pipe was reinforced and strengthen with Wrap Seal PLUS™ Fiberglass Repair Tape.

## **Application Photographs**



SealXpert<sup>™</sup> stainless steel clips and Seal Stic™ was applied onto the pipe to arrest leak



SealXpert™ Repair Putty was applied onto the affected area



Wrap Seal PLUS™ Fiberglass Tape was applied for pipe reinforcement



